



8400 6th St. SW Cedar Rapids, IA 52404 319-365-0551 www.altorfer.com

Bill To:

8693 1 AB 0.593 E0104X I0274 D14364852585 S2 P10822295 0001:0003

որդոՍրվիցՍԱգմեկոդՍկիիցիեմկինոՍկեկինդ



CITY OF BLOOMFIELD 111 W FRANKLIN ST **BLOOMFIELD IA 52537-1696**

Ship To: **WWTP** CITY OF BLOOMFIELD **WWTP** 701 S EAST ST Bloomfield IA

ORIGINAL INVOICE

INVOICE NUMBER **Invoice Date Total Due**

WO400047280 05/23/2025 \$8,104.75

Terms	NET 30
Make	AA
Model	DG350-2GC
Serial #	*CATDG350EKL600133*
Machine ID	20-11045
Equipment #	
Meter Reading	187.0
Document #	CE53644

TO VIEW AND PAY ONLINE: https://altorfer.billtrust.com **USING THIS TOKEN:**

XBM XTX DKK

PLEASE REMIT TO:

ALTORFER INC. PO Box 809629 Chicago, IL 60680-8802

Page 1 of 3

Customer #	Customer PO #	Doc Date	Sales Representative	Division	Store	Account Status
613845	WWTP GEN/PER RUSTY	03/31/2025	610	E	40	2

TROUBLESHOOT ENGINE & GENERATOR

TECH: DUSTIN DATE: 5-21-25

SERIAL NUMBER: KL600133

HOURS:187

CUSTOMER CONCERN: TROUBLESHOOT HARD STARTING. TAKES 2 CRANK CYCLES BEFORE IT WILL START.

CAUSE OF FAILURE: IGNITION MODULE PICKUP SENSOR

RESULTANT DAMAGE: IMPROPER SPARK

REPAIR COMMENTS: 4-1-25: WENT TO SITE. COULD NOT GET UNIT TO START. TESTED GAS PRESSURE, WAS HIGH AT 16" H20, SET PRESSURE TO 11" H20. CHECKED SPARK AND FIND THAT ITS FAINT AND INTERMITTENT ON AT LEAST CYLINDER NO 7. ORDERED NEW SPARK PLUGS AND WILL RETURN.

4-15-25: RETURNED TO SITE. INSPECTED SECONDARY HARNESS FROM ALTRONIC BOX TO COILS. FOUND THAT THE AMPHENOL CONNECTOR AT THE IGNITION BOX HAD A PLUGGED WIRE SOCKET NOT LETTING CONNECTOR GO IN.

610-815-6350 25-111 202

TOTAL AMOUNT DUE

Cont'd

THIS INVOICE AND ALL DOCUMENTS AND TRANSACTIONS RELATED THERETO ARE GOVERNED BY THE TERMS AND CONDITIONS AVAILABLE AT WWW.ALTORFER.COM/TERMS/ (AS REVISED FROM TIME TO TIME, THE "TERMS"), WHICH ARE INCORPORATED BY REFERENCE. ACCEPTANCE OF GOOD OR SERVICES ASSOCIATED WITH THIS INVOICE, OR PAYMENT THEREOF, CONSTITUTES ACCEPTANCE OF AND AGREEMENT TO THE TERMS. A HARD COPY OF THE TERMS IS AVAILABLE UPON REQUEST.





8400 6th St. SW Cedar Rapids, IA 52404 319-365-0551 www.altorfer.com

ORIGINAL INVOICE

INVOICE NUMBER
Invoice Date
Total Due

WO400047280 05/23/2025 \$ 8 104 75

TOTAL DUC	φο, τοπ. το
Terms	NET 30
Make	AA
Model	DG350-2GC
Serial #	*CATDG350EKL600133*
Machine ID	20-11045
Equipment #	
Meter Reading	187.0
Document #	CE53644

Page 2 of 3

Customer #	Customer PO #	Doc Date	Sales Representative	Division	Store	Account Status
613845	WWTP GEN/PER RUSTY	03/31/2025	610	E	40	2

REMOVED HARNESS TO TAKE TO SHOP. ORDERED IN A NEW CONNECTOR.

4-17-25: AT SHOP, DE-SOLDERED OLD CONNECTOR AND RE-SOLDERED NEW ONE ON WITH STRAIN RELIEF. CLOCKED THE CONNECTOR THE CORRECT WAY.

4-18-25: RETURNED TO SITE AND INSTALLED HARNESS BACK ONTO MACHINE. STILL GETTING INTERMITTENT SPARK AND NO START CONDITION. DOUBLE CHECKED POWER AND GROUND CONNECTIONS. BELIEVE PROBLEM IS EITHER IN THE IGNITION MODULE ITSELF OR THE TIMING SENSOR. REMOVED BOX AND TOOK WITH ME, WILL SEE IF ALTRONIC HAS A WAY TO TEST IT. ALTRONIC SAYS ITS GENERAC SPECIFIC BOX. I TOOK BOX TO DUBUQUE TO A SISTER MACHINE AND TESTED IT THERE. ENGINE RUNS FINE. ORDERED TIMING SENSOR.

5-21-25: RETURNED AGAIN TO BLOOMFIELD.
RE-INSTALLED IGNITION BOX. REMOVED OLD TIMING
SENSOR AND INSTALLED NEW ONE, SET AIR GAP. UNIT
NOW STARTS AND RUNS. ADJUSTED THE AIR FUEL
CONTROLLER TO HELP UNIT START EASIER. FOUND LEFT
HAND EXHAUST PIPE HAD PULLED OUT OF MUFFLER.
RE-INSTALLED PIPE AND TIGHTENED CLAMPS BACK UP.
ALTERNATOR BELTS ARE SQUEALING AND LOOSE. THE
TENSIONER IS OUT OF ADJUSTMENT HOWEVER. WILL NEED
TO ORDER NEW BELTS. CUSTOMER JUST SIGNED SERVICE
AGREEMENT SO WILL PROBABLY JUST CHANGE BELTS THEN.

**PRODUCT STATUS REPORT UPLOADED TO WORK ORDER MEDIA TAB.

COMPLICATIONS, IF ANY:

FIELD ENG LABOR

15.50 RT HOURS

46010

2898.50 93.50

FIELD ENG LABOR

0.50 OT HOURS

46010

Cont'd

TOTAL AMOUNT DUE

THIS INVOICE AND ALL DOCUMENTS AND TRANSACTIONS RELATED THERETO ARE GOVERNED BY THE TERMS AND CONDITIONS AVAILABLE AT WWW.ALTORFER.COM/TERMS/ (AS REVISED FROM TIME TO TIME, THE "TERMS"), WHICH ARE INCORPORATED BY REFERENCE. ACCEPTANCE OF GOOD OR SERVICES ASSOCIATED WITH THIS INVOICE, OR PAYMENT THEREOF, CONSTITUTES ACCEPTANCE OF AND AGREEMENT TO THE TERMS. A HARD COPY OF THE TERMS IS AVAILABLE UPON REQUEST.





8400 6th St. SW Cedar Rapids, IA 52404 319-365-0551 www.altorfer.com

ORIGINAL INVOICE

INVOICE NUMBER Invoice Date Total Due WO400047280 05/23/2025 \$ 8 104 75

Total Due	\$ 0,104.75			
Terms	NET 30			
Make	AA			
Model	DG350-2GC			
Serial #	*CATDG350EKL600133*			
Machine ID	20-11045			
Equipment #				
Meter Reading	187.0			
Document #	CE53644			

Page 3 of 3

Customer #	Customer PO #	Doc Date	Sales Representative	Division	Store	Account Status
613845	WWTP GEN/PER RUSTY	03/31/2025	610	E	40	2
1.00 1.00 1.00 3.00	IG/TRANS LABOR	TOTAL SPEC OK626 ENVIF INC TOTAL	LABOR CONNECTOR MAGPICKUP OSSIGN	46010 SEG. 01 46500 46500 66095 15555 SEG. 01		668.00 3660.00 * 203.42 1211.97 25.00 64.36 1504.75 * 5164.75 T

TRAVEL TO/FROM MACHINE

WWTP

CITY OF BLOOMFIELD

WWTP

701 S EAST ST

BLOOMFIELD

ΙA

	TRAVEL	1.50 OT	HOURS 4601T		157.50
	TRAVEL	10.75 RT	HOURS 4601T	<i>y</i>	1128.75
		TOTAL LA	ABOR SEG.	99	1286.25 *
525.00		MILEAGE	64110		1653.75
		TOTAL M	ISC CHGS SEG.	99	1653.75 *
		SEGMEN	T 99 TOTAL		2940.00 T

TAX EXEMPTION LICENSE GOV 2022

PLEASE DIRECT WORK ORDER INQUIRIES TO THE SERVICE DEPARTMENT: PH 319-365-6500

TOTAL AMOUNT DUE

\$ 8,104.75

THIS INVOICE AND ALL DOCUMENTS AND TRANSACTIONS RELATED THERETO ARE GOVERNED BY THE TERMS AND CONDITIONS AVAILABLE AT WWW.ALTORFER.COM/TERMS/ (AS REVISED FROM TIME TO TIME, THE "TERMS"), WHICH ARE INCORPORATED BY REFERENCE. ACCEPTANCE OF GOOD OR SERVICES ASSOCIATED WITH THIS INVOICE, OR PAYMENT THEREOF, CONSTITUTES ACCEPTANCE OF AND AGREEMENT TO THE TERMS. A HARD COPY OF THE TERMS IS AVAILABLE UPON REQUEST.